

 **DAHER**

AIRCRAFT LOG BOOK

PREVIOUS HISTORY

Record to date of flying times: 07 / 11 / 2023

Since last major inspection : hours

Essais en vol le : 07/11/2023

396


(1) These entries must be reproduced in their entirety in each and every subsequent Logbook.

AIRCRAFT RECORD

[illegible]

1

**Stamp and signature or approval
of the maintenance operator**



Static system leak test on : 20-Oct-2023

VISA :



DAHER



AIRCRAFT RECORD



Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs	Make	Model	S/N	A/C TT	ETT	Cycles	PTSN
N11LM	106.8	Daher	TBM700/960	1507	106.8	106.8	64	106.8

1. Completed first 100 hour inspection IAW Daher MM CH 5-20-00.
2. Complied with P&WC SB 77013R1. Inspection of ignition cable assembly. No defects noted.
3. Contacted Hartzell Support. Propeller serial number TZ107 has complied with ASB-405. This propeller was upgraded at the DAHER facility prior to aircraft delivery. According to Hartzell representative John Popel.
4. Sanded, primed, and repainted section of left wing upper middle area. Paint work performed by Mark Paschal.
5. Adjusted left flap actuator nut in 1.5 turns due to right wing heavy condition in flight. Ref MM CH 27-50-00.
6. Performed propeller beta sensor calibration. No defects noted. Ref MM CH 61-20-02.
7. Operational and leak check of all above items found to be satisfactory.

I certify that this Airframe has been inspected in accordance with a 1st 100 Hour inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service.
Details for the repair/inspection are on file at this C.R.S. under Shop Order No. S-23-3103
Date: 1/5/2024 Signed: [Signature] Inspector for Muncie Aviation Company
CRS#AJVR135C, Muncie, Indiana 47303 765-289-7141



Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs	Make	Model	S/N
N11LM	138.1	Daher	TBM 700/960	1507

1. Performed compressor wash and T-wheel rinse. Ref P&WC MM CH 71-00-00.
2. Replaced left aft engine cowling prop rod retaining clip with new, p/n 7478110019.
3. Serviced all tires with nitrogen.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed.
Details are on file at this C.R.S. under Work Order No. S-24-3276
Date 3/18/2024 Signed: [Signature] Inspector for Muncie Aviation Company.
CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141.



Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs	Make	Model	S/N
N11LM	175.9	Daher	TBM 700/960	1507

1. Installed Repaired PCU P/N 3135108-01, S/N WDA145684 Ref Woodward WO 3868830 using new gasket PN 3131743-01. Updated DCTU LRU as required. Grd run, calibrated beta feedback sensor. Op's and leak checks good. Ref CH. 61-20-01 PT6E-66XT MM.
2. Installed new Airframe De-ice Timer P/N 42E25-2A, S/N U1951. Op's checks good. Ref Ch. 30-10-03.
3. Move co-pilots seat back 2 slots.
4. Repaired cabin tray table using Loctite on screws.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed.
Details are on file at this C.R.S. under Work Order No. S-24-3311
Date 4/24/2024 Signed: [Signature] Inspector for Muncie Aviation Company.
CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141.

DAHEF

4



Dates

Reg. Mark
N11LM

Hobbs
304.6

Make
Daher

Model
TBM 700/960

S/N
1507

1. Complied with 1 year autopilot inspection including cable condition and tension check IAW 22-11-03 -04 -05-501, and autopilot clutch manual override check IAW 22-11-00-601
2. Complied with Federal Aviation Regulation 91.207d 1, 2, 3, and 4 ELT checks. Removed ELT. Inspected battery for condition and leakage. Performed ELT and G switch functional test, and reinstalled ELT. All ELT function checks good. Battery expiration date: October 2028
3. Complied with 1 year/200 hour RVSM inspection, Static Port and Dimension check IAW 53-00-00-601.

The article has been repaired and inspected in accordance with current FAA regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed.

Details are on file at this C.R.S under Work Order No.

Date 11/1/2024

Signed [Signature]

A-24-5583

Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141



Reg. Mark	Hobbs	Make	Model	SN	ACTT	ETT	Cycles	PTSN
N11LM	304.6	Socata	TBM 700/960	1507	304.6	304.6	168	304.6

1. Completed an Annual/A+ inspection IAW Daher MM CH 5-20-00.
2. Performed compressor wash and T-wheel rinse.
3. Complied with all applicable 1 year special inspection items
4. Complied with 1 year battery capacity check. Battery passed at 96.6%.
5. Complied with 1 year gaseous oxygen system inspection. No defects noted. Serviced oxygen system to 1850 psi.
6. Complied with 1 year fire extinguisher inspection. No defects noted.
7. Complied with 1 year Auto Throttle Functional test. No defects noted. Ref MM CH 22-30-00.
8. Complied with SB 70-328-24 Battery Discharging, MOD70-0827-92 Ver B, MOD70-760-46 Ver C. Installed kit p/n OPT70K32800. Ref Daher wo 4501217151. IAW SB70-328-24.
9. Complied with SL70-068-32, Main wheel-assembly P/N 40-489 rupture disc torque. Right and left main wheel rupture disc properly torqued and applied torque stripe. Serviced tires with nitrogen. Ref SL70-068-32.
10. Replaced left cabin cup holder with new, p/n SIA005B-0714-BBB. Ref Daher wo 45012068846.
11. Operational and leak of above items check good.

See AD list dated 10/23/2024 for details.

I certify that this Airframe has been inspected in accordance with an Annual/A+ inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S under Shop Order No. S-24-3597 Date 11/4/2024

Signed [Signature]

Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141



Reg. Mark	Hobbs	Make	Model	S/N
N11LM	345.2	Socata	TBM700960	1507

1. Replaced right and left wingtip lenses with new, p/n Left T700H334002410051, Right T700H334002310051.
2. Removed, disassembled, cleaned, reinstalled, and adjusted left main gear actuator down lock limit switches. Cycled gear several times and performed emergency extension. Operational check good. Ref MM CH 32-30-00.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed. Details are on file at this C.R.S. under Work Order No. S-24-3615.
Date: 1/30/2025 Signed: [Signature] Inspector for Muncie Aviation Company. CRS# AJVR135C. Muncie, Indiana 47303. 765-289-7141.



Reg. Mark	Hobbs	Make	Model	S/N
N11LM	390.1	Socata	TBM700960	1507

1. Performed compressor wash and T-wheel rinse IAW PWC MM CH 71-00-00.
2. Replaced Left main tire with new Goodyear tire, p/n 185F03-5, s/n 32930103 using new oring. Ref Goodyear wo 79110888400. Torqued wheel halves and serviced with nitrogen. Ref CMM 32-40-00.
3. Retorqued pilot door handle hardware, cleaned, and lubed mechanism. Operational check good. Ref MM CH 52-12-00.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed. Details are on file at this C.R.S. under Work Order No. S-25-3843.
Date: 4/8/2025 Signed: [Signature] Inspector for Muncie Aviation Company. CRS# AJVR135C. Muncie, Indiana 47303. 765-289-7141.

AIRCRAFT RECORD



Reg. Mark	Hobbs	Make	Model	SN	ACTT	ETT	Cycles	PTT
N11LM	458.3	Socata	TBM 700/960	1507	458.3	458.3	253	458.3

1. Completed an Annual/B+ inspection IAW Daher MM CH 5-20-00.
2. Performed compressor wash and T-wheel rinse.
3. Complied with all applicable 1 year special inspection items
4. **Complied with 1 year Auto Throttle Functional test. No defects noted. Ref MM CH 22-30-00.**
5. **Complied with 1 year gaseous oxygen system inspection. No defects noted. Serviced oxygen system to 1850 psi.**
6. Complied with 1 year main battery capacity check. Battery passed at 104.5%.
7. **Complied with 2 year fire extinguisher inspection. No defects noted.**
8. **Complied with 2 year light weight Data Recorder. No defects noted.**
9. **Complied with 2 year outflow and safety valve seat inspection. No defects noted.**
10. Complied with AD 2025-02-08 Daher Aerospace-Emergency procedures in the existing pilot's operating handbook. Inspected POH and determined current revision to be Rev. 5, TR30 was incorporated into Rev. 5 dated February 5, 2024. POH is in compliance with AD 2025-02-08.
11. **Complied with SB70-260-57-R1 Aileron brush modification. Removed remaining right and left aileron brushes.**
12. SB70-340-32-R1 Electro-Hydraulic Generator Plug Replacement is N/A p/n CEN-S001672 not installed.
13. Replaced cabin step deployment cable with new, p/n T700B526004310100. Set cable tension and torqued hardware. Ref MM CH 52-60-01.
14. Repainted right and left winglet, upper left and right wing, upper and lower forward engine cowlings, vertical and rudder horns. Removed, balanced, and reinstalled rudder after completion of horn painting. Ref MM CH 55-40-00 & 51-60-00. Paint work performed by Mark Paschal.
15. **Replaced left winglet upper static wick with new, p/n 7179110204. Ref MM CH 23-60-00.**
16. Adjusted right and left aileron and spoiler cable tensions within limits and safetied. Verified proper travels. Ref MM CH 27-10-00.
17. Adjusted right and left elevator trim cable tensions within limits and safetied. Verified proper travels. Ref MM CH 27-30-00.
18. Operational and leak of above items check good.

See AD list dated 10/29/2025 for details.

I certify that this **Airframe** has been inspected in accordance with an **Annual/B+** inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S. under Shop Order No. S-25-4087 Date 11/6/2025
Signed: [Signature] Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141

DAHEI

6

Altimeter Scale Correction Card			
Altimeter P/N		6420302-1	
Altimeter S/N		C23-13304	
Test Point Feet	Altimeter Reading	Test Point Feet	Altimeter Reading
-1000	-1000	14000	14025
0	0	16000	16030
500	500	18000	18035
1000	1000	20000	20040
1500	1500	22000	22040
2000	2000	25000	25050
3000	3000	30000	30070
4000	4000	35000	35090
6000	6005	40000	N/A
8000	8010	45000	N/A
10000	10015	50000	N/A
12000	12020		
Tested By: <u>Ziad Ayari</u>			
Inspector: <u>CLW</u>			
Date: <u>11-3-2025</u>			
Muncie Aviation Co. CRS# AJVR135C			
5201 N. Walnut St. Pilot			
Muncie, IN 47303 Stry			

Altimeter Scale Correction Card			
Altimeter P/N		011-03734-40	
Altimeter S/N		4E5100170	
Test Point Feet	Altimeter Reading	Test Point Feet	Altimeter Reading
-1000	-1000	14000	14000
0	0	16000	15995
500	500	18000	17995
1000	1000	20000	19995
1500	1500	22000	21995
2000	2000	25000	24990
3000	3000	30000	29990
4000	4000	35000	34990
6000	6000	40000	N/A
8000	8000	45000	N/A
10000	10000	50000	N/A
12000	12000		
Tested By: <u>Ziad Ayari</u>			
Inspector: <u>CLW</u>			
Date: <u>11-3-2025</u>			
Muncie Aviation Co. CRS# AJVR135C			
5201 N. Walnut St. Pilot			
Muncie, IN 47303 PFD			

Altimeter Scale Correction Card			
Altimeter P/N		011-03734-40	
Altimeter S/N		4E5100186	
Test Point Feet	Altimeter Reading	Test Point Feet	Altimeter Reading
-1000	-1000	14000	14000
0	0	16000	15995
500	500	18000	17995
1000	1000	20000	19995
1500	1500	22000	21995
2000	2000	25000	24990
3000	3000	30000	29990
4000	4000	35000	34990
6000	6000	40000	N/A
8000	8000	45000	N/A
10000	10000	50000	N/A
12000	12000		
Tested By: <u>Ziad Ayari</u>			
Inspector: <u>CLW</u>			
Date: <u>11-3-2025</u>			
Muncie Aviation Co. CRS# AJVR135C			
5201 N. Walnut St. Co Pilot			
Muncie, IN 47303 PFD			

Date Tested: 11/3/2025 P/N 011-03734-40 S/N 4E5100170

Copilot's PFD: Mfg. Garmin P/N 011-03734-40 S/N 4E5100186

Date Tested: 11/3/2025

Pilot's Standby: Mfg. Mid Continent P/N 6420302-1 S/N C23-13304

Date Tested: 11/3/2025

Transponder #1: Mfg. Garmin Model GTX 345D S/N 51Y001780

Transponder #2: Mfg. Garmin Model GTX 335R S/N 3EF026267

Encoder #1: Mfg. Garmin Model GDC 72 S/N 4E5100170

Encoder #2: Mfg. Garmin Model GDC 72 S/N 4E5100186

Details of the inspection are on file at this C.R.S. under Work Order No.: A-25-6153

Date 11/3/2025 Signed CLW Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141

AIRCRAFT RECORD

Details of inspections and maintenance – Minor or major overhauls
Modifications – Test flights

Stamp and signature or approval
of the maintenance operator



Reg. Mark N11LM Hobbs 458.3 Make Daher Model TBM 700/960 S/N 1507

1. Complied with SB70-344-34-R2 Garmin Software update 7.4.2 Rev 1.
2. Complied with 1 year/200 hour RVSM inspection, Static Port and Dimension check IAW 53-00-00-601.
3. Complied with 2 year/400 hour RVSM Inspection: Pitot tube condition check IAW 34-11-00-601; and air data system check IAW 34-11-00-501.
4. Complied with VMO warning check and Pitot-Static leak check IAW 34-11-00-501.
5. Complied with 1 year autopilot inspection including cable condition and tension check IAW 22-11-03,-04,-05-501; and autopilot clutch manual override check for B35, B36, B37, and B38 servo actuators IAW 22-11-00-601.
6. Complied with Federal Aviation Regulation 91.207d 1, 2, 3, and 4 ELT checks. Removed ELT, inspected battery for condition and leakage. Performed ELT and G switch functional test, and reinstalled ELT. All ELT function checks good. Battery expiration date: October 2028.

The article has been repaired and inspected in accordance with current FAA regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed.

Details are on file at this C.R.S under Work Order No. A-25-6153

Date 11/3/2025 Signed CLW Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141