




HARTZELL


PROPELLER LOGBOOK

PROPELLER MODEL _____

PROPELLER S/N _____

LOGBOOK # _____

Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repairs, and Inspections
	TSN	TSO	Hrs	
				wo: RS22-011 Propeller - page 1 of 1  Authorized Service Center Exec Aero, LLC · 83 Nilson Way · Orlando, FL 32803 · 407-420-7934 · CRS#: EXAR968D N970TB Hartzell Propeller, HC-E5N-3C/NC8834K, S/N: RJ597 September 13, 2022 Cycles: 324 Meter: 417.2 SINCE NEW (Meter): 417.2 1. C/W 12Mo/400Hr Periodic inspection of propeller IAW Hartzell Propeller Owner's Manual 147 61-00-47. 2. C/W Hartzell Propeller Inc.HC-SL-61-364 (Corrosion Inhibitor on Counterweights). Installed P/N AV30DME13-5 - Ardrex AV 30 Corrosion Inhibitor Rev/Lot: C232391593. 3. C/W 12Mo Propeller De-Ice Boot Resistance Check IAW Hartzell Propeller Ice Protection Manual 180, 30-61-80 Page 3-102, and Table Q.. 4. 12Mo/600Hr - Complied beta ring dimensional check and replaced carbon block with new IAW Hartzell Propeller Owner's Manual 147 61-00-47, Section 6. 5. C/W 12Mo - Propeller Lubrication - Lubricated propeller hub IAW Hartzell Propeller Owner's Manual 147, Revision 17, September 2020, section 61-10-01-301. 6. Operational and leak checks completed. I certify that this Propeller has been inspected in accordance with a Periodic Inspection and was determined to be in Airworthy condition. With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS22-011. Nathan Marler for CRS EXAR968D 

Date	Propeller		A/C	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repairs, and Inspections
	TSN	TSO	Hrs	
				wo: RS23-046 Propeller - page 1 of 1  Authorized Service Center Exec Aero, LLC · 83 Nilson Way · Orlando, FL 32803 · 407-420-7934 · CRS#: EXAR968D N970TB Hartzell Propeller, HC-E5N-3C/NC8834K, S/N: RJ597 September 07, 2023 Cycles: 544 Meter: 693.0 SINCE NEW (Meter): 693.0 1. C/W 12Mo/400Hr Perform a Periodic Inspection of the propeller IAW Hartzell Manual 147 61-00-47. 2. C/W 12Mo Propeller lubrication IAW 61-10-01. 3. C/W 1Yr Propeller de-ice boot resistance check IAW Propeller Ice Protection Manual 180, 30-61-80. 4. C/W 1Yr Perform a detailed inspection of non-rotating or airframe mounted components IAW 61-00-00. 5. C/W 1Yr/400Hr Propeller apply corrosion inhibitor to steel components IAW 61-10-01. 6. C/W 1Yr/600Hr Beta ring and carbon block dimensional check IAW 61-10-00. Replaced beta carbon block IAW 61-10-00. Installed P/N 6036387238 (Alt A-3026) - Carbon brush block Rev/Lot: BF224. 7. C/W Propeller operational and leak checks. I certify that this Propeller has been inspected in accordance with a Periodic Inspection and was determined to be in Airworthy condition. With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS23-046. Nathan Marler for CRS EXAR968D 

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.			
	TSN	TSO					
  							
	Reg. Mark	Hobbs	Make	Model	SN	ACTT	PTT
	N970TB	910.2	Hartzell	HC-E5N-3C	RJ597	910.2	910.2
1. Completed an Annual/C+ inspection IAW Daher MM CH 5-20-00. 2. Complied with 1 year Beta Ring and Carbon block inspection. Replaced carbon block with new, p/n CA3044 Ref. Hartzell Manual 147. 3. Operational and leak check of above items good.							
See AD list dated 9/13/2024 for details. I certify that this Propeller has been inspected in accordance with an <u>Annual/C+</u> Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S under Shop Order No. <u>S-24-3505</u> Date <u>9/17/2024</u> Signed <u>[Signature]</u> Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141							

  							
	Reg. Mark	Hobbs	Make	Model	SN	ACTT	PTT
	N970TB	1097.1	Hartzell	HC-E5N-3C	RJ597	1097.1	1097.1
1. Completed an Annual/A+ inspection IAW Daher MM CH 5-20-00. 2. Complied with 1 year Beta Ring and Carbon block inspection. Replaced carbon block with new, p/n CA3044 Ref. Hartzell Manual 147. 3. Operational and leak check of above items good.							
See AD list dated 9/8/2025 for details. I certify that this Propeller has been inspected in accordance with an <u>Annual/A+</u> Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S under Shop Order No. <u>S-25-4018</u> Date <u>9/12/2025</u> Signed <u>[Signature]</u> Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141							