

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL 5D3-N338A1

PROPELLER S/N SF150

LOGBOOK # 1

Date

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Propeller Log


Date: 10/3/18 Hobbs Time: 1.7

Aircraft S/N: 4698090 Reg. Number: N603MA

Prop Model: 5D3-N338A1 S/N: SF 150

Complied with Hartzell Propeller Owner's Manual 149.

6-5 THRU 6-9
Performed Lubrication of Prop by Manufacturer during Flight
Testing with Aeroshell #6 after 1 to 2 hours operation.

Signature: 

Name: David T Wallace Jr A&P Certificate Number: AP51627416



PIPER AIRCRAFT, INC.



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs/Tach	Make	Model	S/N	A/C TT	ETT	Cycles	Prop
N603MA	182.4	Hartzell	5D3-N338A1	SF150	182.4	182.4	195	182.4

Annual Inspection completed this date Ref Piper Inspections Events #1 & #2

Installed New BETA Block unit P/N CA3044

I Certify that this Propellor has been inspected in accordance with a Annual Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current Regulations of Federal Aviation Agency, approved for return to service.

Details of the repair/inspection are on file at this C.R.S under Shop Order No. S-19-1056

Date 11/12/2019 Signed  Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141

Date | Propeller | A/C | Description of all operations



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs/Tach	Make	Model	S/N	A/C TT	ETT	Cycles	Prop
N603MA	346.1	Hartzell	5D3-N338A1	SF150	346.1	346.1	300	346.1

Annual Inspection completed this date Ref Piper Inspections Events #1 & #2

I Certify that this Propellor has been inspected in accordance with a Annual Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current Regulations of Federal Aviation Agency, approved for return to service.

Details of the repair/inspection are on file at this C.R.S under Shop Order No. S-20-1629

Date 12/14/2020 Signed [Signature] Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs/Tach	Make	Model	S/N	A/C TT	ETT	Prop
N603MA	486	Hartzell	5D3-N338A1	SF150	486	486	486

Annual Inspection completed this date Ref Piper Inspections Events #1 & #2

I Certify that this Propellor has been inspected in accordance with a Annual Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current Regulations of Federal Aviation Agency, approved for return to service.

Details of the repair/inspection are on file at this C.R.S under Shop Order No. S-21-2104

Date 12/3/2021 Signed [Signature] Inspector For Muncie Aviation Company

CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141

Da



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs/Tach	Make	Model	S/N	A/C TT	PTSOH
603MA	590.4	Hartzell	5D3-N338A1	SF150	590.4	590.4

1. Completed Annual Inspection IAW Piper Inspection Report P/N 767-008.
2. Operational and leak check of above items found to be satisfactory.

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service.

Details for the repair/inspection are on file at this C.R.S under Shop Order No. S-22-2553
 Date: 11/18/2022 Signed: [Signature] Inspector for Muncie Aviation Company
 CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs	Make	Model	S/N	A/C TT	PTSN
N603MA	848.0	Hartzell	5D3-N338A1	SF150	848.0	848.0

1. Completed an Annual inspection IAW Piper MM CH 5-20-00.
2. Complied with 1 year Beta Ring and Carbon block inspection. Replaced beta block with new CA3044. Ref MM CH 61-10-00.
3. Operational and leak check of above items found to be satisfactory.

See AD Listing Dated 11/16/2023 for Details.

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service.

Details for the repair/inspection are on file at this C.R.S under Shop Order No. S-23-2967
 Date: 11/21/2023 Signed: [Signature] Inspector for Muncie Aviation Company
 CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141
