



Transport
Canada

Transports
Canada

TP 14182
(Revised 05/2005)

Engine Logbook

GAS GENERATOR MODULE LOG BOOK

TC-1001185



05/2005

Canada

Volume #: 1
Opened on: 29 JUN 2021

ENGINE DETAILS

1. Manufacturer Pratt & Whitney Canada Corp.
2. Type/Model/Series E.T.C. E- 21 PT6A- 66 D B/S: 1354
3. Serial Number PCE- RV0738

Other related Transport Canada Publications:
TP 14089B
TP 14058E/F

Previous Edition:
TP 3910E, 2nd Edition (Jan. 1987)
TP 14182E (Dec. 2003)

Printed in Canada.

Please direct your comments, orders and inquiries to:

Transport Canada
Civil Aviation Communications Centre (AARC)
Place de Ville,
Tower C, 5th Floor
330 Sparks Street
Ottawa, ON K1A 0N8

Telephone: 1 800 305-2059
Fax: 613 957-4208
E-mail: services@tc.gc.ca

© Her Majesty the Queen in Right of Canada, as represented by the Minister of Transport (2005).
® Permission granted for internal use only:

This publication may be reproduced for internal use only without permission, provided the source is fully acknowledged. However, multiple copy reproduction of this publication in whole or in part for purposes of resale or redistribution requires prior written permission from the Minister of Public Works and Government Services, Ottawa, Ontario, Canada K1A 0S5 or at copyright.droitdauteur@communication.gc.ca.

TP 14182E
(05/2005)
TC-1001185
Catalogue No. T52-4/2-2003E

Date --/--/--	Time since new	Time since overhaul	Total cycles	Details of task
29 JUN 2021	0.0	N/A	0	New engine final acceptance test and inhibiting run completed satisfactorily and is in condition for safe operation.
30 JUL 2021	0 ^h 50	0.0	1	Vols d'essai constructeur
01 SEPT 2021	2 ^h 35	0.0	2	
08 SEPT 2021	3 ^h 40	0.0	3	
09 SEPT 2021	4 ^h 35	0.0	4	
Arrêté présent livret à la Cie DAHER le 08/09/2021 au total de 4^h 35 Visa du Département Qualité <i>Philippe</i>				



Section 1: Record of engine maintenance and elementary work

DAHER

Date : 09/21/2021

Meter Time: 24.2 Hobbs

FAA CRS # URZR891L / EASA.145.5152

Serial Number : 1389

Time Since New : 24.2

Registration : N970TB


Cycle Since New : 10

Daher Aircraft, Inc.
601 NE 10th Street
Pompano Beach, FL 33060

Aircraft type : TBM 700N

Work Order : 7425

- Eng. PT6A-66D, S/n: PCE-RV0738, TSN. 24.2, CSN. 10
- Complied with FOD visual inspection of first stage compressor blades IAW P&WC maintenance manual chapter 72-30-05 with no discrepancies being noted.
- C/W P&WC SIL PT6-213 Inspection of compressor inlet case for corrosion, no corrosion found at this time. Applied approved corrosion inhibitor compound "Corrosion X" on inlet case area as required IAW P&WC EMM Section 72-00-00 as specified in P&WC Service Information Letter No. PT6A-213.
- C/W engine compressor performance recovery wash IAW Pratt & Whitney maintenance manual Part No. 3070902, Revision No.17.1, Dated AUG 18/2016 Chapter 71-00-00. Operational check performed with no discrepancies being noted at this time.

The aircraft Airframe, Engine, Propeller, Appliance Identified Above Was Repaired And Inspected In Accordance With Current Regulation Of Federal Aviation Administration And In Accordance With EASA 145.A.50 And Is Approved For Return To Service For the Work Performed. Permanent Records Of The Repair Are On File At This Repair Station Under W.O. # 7425,
Date : 09/21/2021 Signature:  Darren SEAGO
CRS # URZR891L / EASA. 145.5152

wo: WO21-767



Engine - page 1 of 1

Exec Aero LLC - 83 Nilson Way - Orlando, FL 32803 - 4074207934

N970TB
Cycles: 57

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 74.6
SINCE NEW: 74.6

November 09, 2021

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 3010880 - GASKET , Rev/Lot: 12172004/9311896118.
2. Operational check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO21-767.

John Polulech Inspection Authorization 3464528

wo: WO21-874



Engine - page 1 of 1

Exec Aero LLC - 83 Nilson Way - Orlando, FL 32803 - 4074207934

N970TB
Cycles: 98

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 126.2
SINCE NEW: 126.2

December 23, 2021

1. Performed engine desalination wash IAW 72-00-00. Installed (2) P/N 3010880 - GASKET , Rev/Lot: 06292101/5862899.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO21-874.

John Polulech Inspection Authorization 3464528

wo: WO22-074



Engine - page 1 of 1

Exec Aero LLC - 83 Nilson Way - Orlando, FL 32803 - 4074207934

N970TB
Cycles: 99

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 180.2
SINCE NEW: 180.2

February 07, 2022

1. Performed engine desalination wash IAW 72-00-00. Installed (2) P/N 3010880 - GASKET Rev/Lot: 06292101/5862899.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO22-074.

John Polulech Inspection Authorization 3464528

wo: WO22-181



Engine - page 1 of 1

Exec Aero LLC - 83 Nilson Way - Orlando, FL 32803 - 4074207934

N970TB
Cycles: 99

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 242.4
SINCE NEW: 242.4

March 23, 2022

1. Performed engine desalination wash IAW 72-00-00. Installed (2) P/N 3010880 - GASKET Rev/Lot: 03152203/IJ13791884.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO22-181.

John Polulech Inspection Authorization 3464528

wo: WO22-104



Engine - page 1 of 1

Exec Aero LLC - 83 Nilson Way - Orlando, FL 32803 - 4074207934

N970TB
Cycles: 99

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 205.2
SINCE NEW: 205.2

February 25, 2022

1. C/W P&WC Engine Minor Inspection IAW 72-00-00 Table 601 Installed P/N AS 560 - TURBINE OIL Rev/Lot: 07272101/9312704914, Installed P/N AS 560 - TURBINE OIL Rev/Lot: 07272101/9312704914.
2. C/W P3 filter ultrasonic cleaning IAW 73-10-07.
3. C/W 12Mo/200Hr Clean /Inspect P3 Filter drain valve housing assembly IAW 73-30-CA. Installed P/N MS9386-014 - Packing Preformed Pratt & Whitney Rev/Lot: 05042001/9311074379, Installed P/N MS9386-015 - Packing Preformed Pratt & Whitney Rev/Lot: 05042001/9311074379, Installed P/N MS9386-126 - Packing Preformed Pratt & Whitney Rev/Lot: 10301901/931022310d.
4. C/W 12Mo/200Hr Check magnetic chip detectors for continuity IAW 79-00-CA. Installed (2) P/N AS3209-115 - Oring Rev/Lot: 03022001/IJ11676025j.
5. C/W 12Mo/200Hr Examine the oil filter element and secondary screen IAW 79-00-CA. Installed P/N AS3209-120 - Seal Rev/Lot: 02182103/IJ12621583, Installed P/N AS3209-143 - Seal Pratt & Whitney Rev/Lot: 05042001/9311074379, Installed P/N AS3209-224 - O RING Rev/Lot: 02182103/IJ12621583.
6. Operational and leak checks completed.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO22-104.

John Polulech Inspection Authorization 3464528

Section

wo: WO22-351

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934

N970TB
Cycles: 99Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 314.0
SINCE NEW (Meter):
314.0

June 03, 2022

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 3010880 - GASKET Rev/Lot: 03152203/IJ13791884, Installed P/N 3023431 - Gasket Rev/Lot: 05122201/IJ13960009.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero LLC under work order: WO22-351.

Nathan Marler Inspection Authorization 3466392

wo: RS22-007

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB
Cycles: 287Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 367.4
SINCE NEW (Meter):
367.4

July 22, 2022

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 3010880 - GASKET Rev/Lot: 03152203/IJ13791884, Installed P/N 3023431 - Gasket Rev/Lot: 0516222.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS22-007.

John Polulech For CRS EXAR968D

 StandardAero		Engine Log Book Entry 2988 West Walnut Hill Lane DFW Airport, TX 75261		Work Order Number: 00033087/ FS71861	Date: 09-08-2022
Aircraft Type: TBM-700.1389	Aircraft Registration Number: N970TB	Aircraft Serial Number: 1389	Aircraft Total Time: 417.2		
Engine S/N: PCE-RV0738	Engine Model: PT6A-66D	Engine Position: Center	Aircraft Total Landings: 324		
Engine Time Since New (TSN): 417.2	Engine Cycles Since New (CSN): 324	Time Since Overhaul (TSO):	Cycles Since Overhaul (CSO):		
Work Performed:					

Work Performed: ACCOMPLISH A 400 HOUR BORESCOPE INSPECTION. ALL WORK ACCOMPLISHED WITH REFERENCE TO THE PRATT & WHITNEY CANADA PW PT6A-66D MAINTENANCE MANUAL PART # 3070902, REVISION 22.0 DATED APR 11 / 2022, CHAPTER 72-00-00. and other data and methods acceptable to the administrator. This certifies that the work requested by the customer and described on the sales order listed above was accomplished and inspected with reference to instructions for continued airworthiness, other data acceptable to the FAA and current FAA regulations, and with respect to the work performed, is approved for return to service. Pertinent details of this repair are on file at this FAA Certified Repair Station.

Signature

Jim Aiken for Standard Aero
FAA CRS # YRRR491L

Given the nature of borescope instrumentation it is often not possible to make observations and examine all areas of an individual engine as part of an evaluation. Based on this limitation, Standard Aero cannot and does not warrant its findings for borescope evaluations (pre-purchase and otherwise) against the possibility that hidden damage may exist that was not observable and reported by our technician at the time of the evaluation.

wo: RS22-011

Engine - page 1 of 2



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB
Cycles: 324Pratt & Whitney Canada, PT6A-66D, S/N: RVO738
Meter: 417.2
SINCE NEW (Meter):
417.2

September 13, 2022

1. C/W P&WC Engine Minor Inspection IAW 72-00-00 Table 601 Installed P/N 7423060092 - Packing Preformed Pratt & Whitney Rev/Lot: TDBS37, Installed P/N MS9386-015 - Filter O-Ring Rev/Lot: TKDS37, Installed P/N MS9386-126 - Packing Preformed Pratt & Whitney Rev/Lot: 0000122369, Installed (2) P/N 7423510012 - Gasket Rev/Lot: 3Q21, Installed P/N 7423510009 - O-Ring (AS3209-143) Rev/Lot: VCD2V46, Installed P/N 7423510008 - Pratt & Whitney Gasket (AS3209-120) Rev/Lot: 0080393625, Installed P/N 7423510010 - O-Ring (AS3209-224) Rev/Lot: VDAV46, Installed P/N 7423510010 - O-Ring (AS3209-224) Rev/Lot: VDAV46.
2. C/W P&WC SIL PT6A-213 compressor inlet case corrosion inspection - Inspected engine compressor inlet case for corrosion, no corrosion noted. Applied CorrosionX corrosion inhibitor on inlet case area IAW P&WC EMM Section 72-00-00 as specified in P&WC Service Information Letter No. PT6A-213.
3. C/W 1Yr P3 Filter Cleaning - Removed Pneumatic P3 Filter, cleaned and reinstalled IAW 72-20-00.
4. C/W 12Mo/200Hr Clean /Inspect P3 Filter drain valve housing assembly IAW 73-30-CA.
5. C/W 12Mo/200Hr Check magnetic chip detectors for continuity IAW 79-00-CA.
6. Performed T5 internal loop and insulation resistance check and found satisfactory 1.5 ohms IAW P&WC PT6A-66D EMM, 77-20-01 Paragraph 9, Sub-Paragraph D.
7. C/W 12Mo/200Hr Examine the oil filter element and secondary screen IAW 79-00-CA.
8. C/W 12Mo/200Hr Engine compressor and compressor turbine (CT) desalination wash IAW Daher TBM maintenance manual chapter 71-00-00 and Pratt & Whitney Canada PT6A-66D maintenance manual chapter 71-00-00.
9. C/W 400Hr Leak Test and Function Test Fuel Manifold Adapter and Nozzle Assemblies - Removed fuel manifold adapters, sent out to Dallas Airmotive CRS YRR6491L, Inc for leak and function check (WO#RPR60485), reinstalled fuel manifold adapters IAW P&WC PT6A-66D EMM 73-11-05. Performed functional leak check, no leaks noted.

ME
AMO
AMO

wo: RS22-011

Engine - page 2 of 2



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

10. 400 Hour - Engine Hot Section Borescope Inspection - Engine hot section borescope inspection performed by StandardAero CRS YRRR491L, refer to WO: 33087.
11. C/W 400Hr Check Ignition Exciter for Installation and Condition - Inspected ignition exciter installation and condition IAW PWC PT6A-66D EMM 74-10-00, Inspection/Check.
12. C/W 400Hr Check Ignition Exciter for Installation and Condition - Inspected ignition cables for chafing, wear, and installation IAW PWC PT6A-66D EMM 74-20-00, Inspection/Check.
13. C/W 400Hr Check Spark Igniters for Cleanliness and Erosion - Checked spark igniters for cleanliness and erosion and performed function check IAW PWC PT6A-66D EMM 74-20-00, Inspection/Check. Replaced igniters. Installed (2) P/N 6069607224 - Igniter (CH34055) Rev/Lot: 7365784325, Installed (2) P/N 742351000 - Gasket, igniter Rev/Lot: 7365678624.
14. Performed oil sampling procedure IAW Pratt & Whitney Canada EMM 72-00-00 Engine, turboprop, servicing, section 5 oil lubrication system, Paragraph D and sent to AvLab for analysis. Installed P/N 560-1QT - Aeroshell Turbine Oil Rev/Lot: 0000011180, Installed P/N 560-1QT - Aeroshell Turbine Oil Rev/Lot: 0000011180, Installed P/N GA-001-OFRK - AVLAB TEST KIT, Installed (10) P/N 560-1QT - Aeroshell Turbine Oil.
15. Performed engine oil servicing by draining engine oil IAW Pratt & Whitney Canada EMM 72-00-00, Turboprop, Servicing, Section 5 Oil Lubrication System, Paragraph E.
16. Operational and leak checks completed.

I certify that this Engine has been inspected in accordance with a Minor Inspection and was determined to be in Airworthy condition.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS22-011.

Nathan Marler for CRS EXAR968D

Section 1:

wo: RS22-011

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB

Cycles: 324

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738

Meter: 417.2

SINCE NEW (Meter):
417.2

September 13, 2022

1. C/W 12Mo/200Hr engine desalination wash IAW 72-00-00.
2. Operational check completed.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS22-011.

Nathan Marler for CRS EXAR968D

wo: RS22-025

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB

Cycles: 385

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738

Meter: 492.9

SINCE NEW (Meter):
492.9

December 09, 2022

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 7423510000 - Ignitor Gasket (3010880) Rev/Lot: 4501040394, Installed P/N 3023431 - Gasket Rev/Lot: 3233385.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS22-025.

Nathan Marler for CRS EXAR968D

wo: RS23-015

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB

Cycles: 437

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738

Meter: 554.1

SINCE NEW (Meter):
554.1

March 01, 2023

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 3023431 - Gasket Rev/Lot: 3220178, Installed P/N 7423510000 - Ignitor Gasket (3010880) Rev/Lot: 7365866024.
2. Operation and leak check complete.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS23-015.

Nathan Marler for CRS EXAR968D

wo: RS23-025

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB

Cycles: 502

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738

Meter: 629.9

SINCE NEW (Meter):
629.9

June 07, 2023

1. Performed engine desalination wash IAW 72-00-00. Installed P/N 3023431 - Gasket Rev/Lot: 3233385, Installed P/N 7423510000 - Ignitor Gasket (3010880) Rev/Lot: 7365866024.
2. Operational and leak checks completed.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS23-025.

John Polulech For CRS EXAR968D

wo: RS23-046

Engine - page 1 of 1



Exec Aero, LLC - 83 Nilson Way - Orlando, FL 32803 - 407-420-7934 - CRS#: EXAR968D

N970TB

Cycles: 544

Pratt & Whitney Canada, PT6A-66D, S/N: RVO738

Meter: 693.0

SINCE NEW (Meter):
693.0

September 07, 2023

1. C/W P&WC Engine Minor Inspection IAW 72-00-00 Table 601. Installed P/N 3010880 - Gasket, P&W Rev/Lot: 7365850921.
2. C/W engine compressor 1st stage FOD Inspection required.
3. C/W P&WC SIL PT6A-213 (Compressor Inlet Case Corrosion Inspection).
4. C/W 1Yr Service engine oil system IAW 79-00-CA. Installed (2) P/N 560-1QT - Aeroshell Turbine Oil Rev/Lot: 0000047089U076, Installed (2) P/N 560-1QT - Aeroshell Turbine Oil Rev/Lot: 0000033084U076.
5. C/W 1Yr Clean P3 filter IAW PWC EMM 73-10-07 Par. 7A. Installed P/N 7423060092 - Seal (MS9386-014) Rev/Lot: TDBS37, Installed P/N MS9386-126 - O RING Rev/Lot: Batch0018243880/ICB 775299-03, Installed P/N MS9386-015 - Filter O-Ring.
6. C/W 1Yr/200Hr Engine desalination wash IAW 72-00-00. Installed P/N 7423510000 - Ignitor Gasket (3010880), Installed P/N 3023431 - Gasket.
7. C/W 200Hr Oil filter and secondary screen inspection IAW 79-20-02. Installed P/N 7423510009 - O-Ring (AS3209-143) Rev/Lot: 765703-03, Installed P/N 7423510008 - Pratt & Whitney Gasket (AS3209-120), Installed P/N 7423510010 - O-Ring (AS3209-224) Rev/Lot: VDAV46.
8. C/W 200Hr AGB internal scavenge pump inlet screen IAW 72-00-00.
9. C/W 200Hr Fuel outlet filter inspection IAW 73-10-02. Installed P/N M25988-1-916 - Oring Rev/Lot: ICN715059/Batch 68688, Installed P/N M25988-1-212 - O-Ring 7/8 in ID, 1-1/8 in Thick, Fluorosilicone Rubber Rev/Lot: 016986994, Installed P/N M25988/1-928 - O-ring PT6 Rev/Lot: 0031008894.
10. C/W 600Hr Fuel pump outlet filter replacement IAW 73-10-02.
11. C/W Engine operational and leak checks.

I certify that this Engine has been inspected in accordance with a Minor Inspection and was determined to be in Airworthy condition.

With respect to the work performed, this engine is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS23-046.

Nathan Marler for CRS EXAR968D



MAC
Muncie Aviation Company
An Employee Owned Company



Reg. Mark	Hobbs	Make	Model	S/N	AC TT	ETT
N970TB	770.8	P&WC	PT6A-66D	PCE-RV0738	770.8	770.8

1. Removed #13 fuel nozzle and performed borescope inspection. No defects noted. Uploaded pictures to MAC server. Reinstalled nozzle using new gasket and orings. Torqued and safetied. Ground run and leak check good. Ref MM CH 73-11-05.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed.

Details are on file at this C.R.S. under Work Order No. S-23-3096
Date 12/18/2023 Signed [Signature] Inspector for Muncie Aviation Company.
CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141.

Section 1: Record of engine maintenance and elementary work



Reg. Mark	Hobbs	Make	Model	S/N	A/C TT
N970TB	818.5	P&WC	PT6A-66D	PCE-RV0738	818.5

1. Complied with AD 2024-04-51 Failure of second-stage power turbine (PT2) blades. Logbook research revealed AD is not applicable by second-stage power turbine (PT2) blades serial numbers. Blade serial numbers are not in the affected range. Ref P&WC SB A14574R1 Table 1. No further action required.

The article has been repaired and inspected in accordance with the current FAA Regulations and was determined to be airworthy with respect to the maintenance, preventative maintenance or alterations performed. Details are on file at this C.R.S. under Work Order No. S-24-3250
Date 2/28/2024 Signed [Signature] Inspector for Muncie Aviation Company.
CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141.



Reg. Mark	Hobbs	Make	Model	SN	ACTT	ETT	Cycles
N970TB	910.2	P&WC	PT6A-66D	RV0738	910.2	910.2	713

1. Completed an Annual/C+ inspection IAW Daher MM CH 5-20-00.
2. Performed compressor wash and T-wheel rinse.
3. Complied with all applicable 1 year special inspection items.
4. Complied with 400 hour fuel manifold adapters inspection. Removed and reinstalled nozzles after inspection by Standard Aero, Ref Standard Aero wo RPR64485, using new orings and gaskets, torqued and safetied. Ref. P&WC MM CH 73-10-03.
5. Complied with 400 hour borescope inspection. No defects noted.
6. Complied with 1,000 hour P3 filter replacement. Replaced filter with new, p/n, 3059788-01. Ref P&WC MM CH 73-10-07.
7. Complied with 1,000 hour oil filter replacement. Replaced filter with new, p/n, 3059258-01. Ref P&WC MM CH 79-20-02.
8. Complied with P&WC SB A14575 Inspection of first stage power turbine (PT1) blades. Logbook research revealed SB is not applicable due to engine not being repaired or overhauled since June 1, 2023. Ref P&WC SB A14575. No further action required.
9. Complied with SB70-310-24 R1. Starter-Generator bearing replacement. Replaced starter generator with overhauled unit p/n MG94K-1, s/n 0143 Mod A. Ref Ametek wo V157991. Torqued and safetied mounting hardware. Ref MM CH 24-30-03.
10. Blended minor erosion on compressor inlet blades. Ref PWC MM CH 72-30-05.
11. Operational and leak check of above items good.

See AD list dated 9/13/2024 for details.
I certify that this Engine has been inspected in accordance with an Annual/C+ Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S under Shop Order No. S-24-3505 Date 9/17/2024
Signed [Signature] Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141



Reg. Mark	Hobbs	Make	Model	SN	ACTT	ETT	Cycles	PTT
N970TB	1097.1	P&WC	PT6A-66D	RV0738	1097.1	1097.1	797	1097.1

1. Completed an Annual/A+ inspection IAW Daher MM CH 5-20-00.
2. Performed compressor wash and T-wheel rinse.
3. Complied with all applicable 1 year special inspection items.
4. Operational and leak check of above items good.

See AD list dated 9/8/2025 for details.
I certify that this Engine has been inspected in accordance with an Annual/A+ Inspection and was determined to be in airworthy condition. The aircraft/component identified above was repaired and inspected in accordance with current regulations of Federal Aviation Agency, approved for return to service. Details for the repair/inspection are on file at this C.R.S under Shop Order No. S-25-4018 Date 9/12/2025
Signed [Signature] Inspector for Muncie Aviation Company CRS# AJVR135C, Muncie, Indiana 47303. 765-289-7141



Transport
Canada

Transports
Canada

TP 14182
(Revised 05/2005)

Engine Logbook

POWER SECTION MODULE LOG BOOK

TC-1001185



05/2005

Canada

Volume #: 1
Opened on: 29 JUN 2021

ENGINE DETAILS

1. Manufacturer Pratt & Whitney Canada Corp.
2. Type/Model/Series E.T.C. E- 21 PT6A- 66D B/S: 1354
3. Serial Number PS- RV0738

Other related Transport Canada Publications:
TP 14089B
TP 14058E/F

Previous Edition:
TP 3910E, 2nd Edition (Jan. 1987)
TP 14182E (Dec. 2003)

Printed in Canada.

Please direct your comments, orders and inquiries to:

Transport Canada
Civil Aviation Communications Centre (AARC)
Place de Ville,
Tower C, 5th Floor
330 Sparks Street
Ottawa, ON K1A 0N8

Telephone: 1 800 305-2059
Fax: 613 957-4208
E-mail: services@tc.gc.ca

© Her Majesty the Queen in Right of Canada, as represented by the Minister of Transport (2005).
® Permission granted for internal use only:

This publication may be reproduced for internal use only without permission, provided the source is fully acknowledged. However, multiple copy reproduction of this publication in whole or in part for purposes of resale or redistribution requires prior written permission from the Minister of Public Works and Government Services, Ottawa, Ontario, Canada K1A 0S5 or at copyright.droitdauteur@communication.gc.ca.

TP 14182E
(05/2005)
TC-1001185
Catalogue No. T52-4/2-2003E

[illegible]

Details are on file at this C.R.S. under Work Order No. S-24-3250
Date 2/28/2024 Signed [Signature] Inspector for Muncie Aviation Company.
CRS# AJVR135C, Muncie, Indiana 47303 765-289-7141.